25X1A Approved (F. or Stell 1881) 2001/03/06 R. OCURT	TY INFORMATION NO
TOPIC Hungarian Airfields Provided with Concr 25X1A	v I
25X1X EVALUATIONPLACE OBTAINE 25X1C DATE OF CONT	D
DATE OBTAINED  REFERENCES	PREPARED 6 December 1951
PAGES ENCLOSURES (NO. & TYPE)	Booument Ro.
	Alth: Dale: Aug 20
25X1X	19/8 PO

SOURCE

25X1X

with a concrete runway, 2,400 meters long and 80 meters wide. The concrete surface of the runways was 30 cm and 22 cm for the taxiways. For the construction of the runways the ground was dug 80 cm deep. The base of the runway consisted of grazel topped by a concrete surface.


- 2. Papa (P 48/Y 30) airfield, code designation G 2, had an old concrete runway, 2,000 meters long and 70 cm wide. The concrete surface was 13 cm thick. A 3-cm asphalt layer was applied to the old concrete surface. This layer was then topped by a new 8-cm concrete layer. A second and new concrete runway of the field was 2,200 meters long, 70 meters wide, and its concrete surface was 22 cm thick. Concrete taxiways were also available. (1)
- 3. Toekoel (Q 48/H 40) airfield, code designation G 3, had a runway 2,200 meterw long and 70 meters wide. The concrete surface of the runway was 22 cm thick. The southeastern portion of the runway was reinforced. The length could not be determined
- 4. Taszar (Y 5/B 06) airfield, code designation G 4, had a concrete runway, 2,500 meters long and 70 meters wide. Its concrete surface was 22 cm thick. When this runway was built, the earth was mixed with cement, sprinkled with water, and then rolled. The concrete was then applied to the rolled ground.
- 5. Kunmadaras (R 48/J 80) airfield, code designation G 5, had a concrete runway 2,500 meters long and 70 meters wide. Its concrete surface was 22 cm thick. 27 aircraft revetment boxes and concrete taxiways were also available at the field. (2)
- 6. Debrecen (R 48/K 40) airfield, code designation G 6, had a concrete runway, 2,500 meters long and 70 meters wide. Its concrete surface was 22 cm thick. A strip of 800 meters in the eastern portion of the runway was reinforced.
- Approved For Release 2001/03/06: CIA-RDP82-00457R009900070006-4

  Szentrikalyszabadja (P 48/D 78) airfield, code designation G 7, was not provided with concrete runways. The terrain of the field was stony and hard.

## Approved For Release 2001/03/96NTG/A-RDP82-00457R009900070006-4~

## SECRET/CONTROL US OFFICIALS ONLY

25X1A



8. Kecskemet (Y 6/N 95) airfield, code designation G 8, had a runway 2,200 meters long and 70 meters wide. Its concrete surface was 22 cm thick.

100

- 9. Madocsa airfield, south of Budapest, west of the Danube Rivery code designation G 9, was not provided with concrete runways or taxiways. The construction of a taxiway is planned for 1952. Excavation work for this purpose had already started. (3).
- 10. Kiskunlachaza (Q 48/N 49) airfield, code designation G 10, had a concrete runway 2,200 meters long and 70 meters wide. Its concrete surface was 22 cm thick.
- 11. Szolnok-Rakoczifalva (Q 48/0 38) airfield, code designation G 11, had a concrete runway 2,200 meters long and 70 meters wide. Its concrete surface was 22 cm thick. (4)
- The construction of a concrete runway is planned at Miskelo (R 49/J 97) airfield, code designation G 12, at Szekesfehervar-Sosto (Q 48/E 09) airfield, and at Balaton-Kiliti (Y 5/D 86) airfield, designation G 14.
  - 13. The concrete used for the construction of the conwave consists of a mix

25X1A

## Comments.

- (1) This statement indicates that Papa airfield was provided with two runways.

  This information requires confirmation, because it was previously reported that only one runw
- (2) The existence of a time. The informa time are gard to the status of the field.
- (3) The existence of an airfield at Madosca is reported for the first time. The pinpoint location of this field could not be determined on maps available.
- (4) The existence of a runway at Szolnok-Rakoczisalve airfield is reported for the first time. However, the existence of a runway there was mentioned in a previous report. Confirmatory information is required.
- (5) This compilation of data on the runways available at Hungarian airfields appears credible, since most of this information confirms previous information.

CONFIDENTIAL SECRET/CONTROL/US OFFICIALS ONLY